



# Dam Safety Inspection Form

State of Oregon  
Water Resources Department  
725 Summer Street NE, Suite A  
Salem, Oregon 97301-1271  
(503) 986-0900

Name of Dam: WALLOWA File #: W-2  
Height: 39 ft. Storage: 49257 ac. ft. Permit: \_\_\_\_\_ NID #: OR- 00465  
Hazard: ☐ Low ☐ Significant ☐ High Inspector(s): MOUS, JANICK, BATES District: 7  
Others on site: MEMBERS OF ASSOCIATED DITCH CO.  
Date: 6/01/2017 Temperature: \_\_\_\_\_ °F ☒ Dry ☐ Rain ☐ Snow ☐ Now ☐ Recently  
Prior Inspection Date: 8/5/2016 Issues from prior inspection: \_\_\_\_\_

**Rating Criteria:** 5-Exemplary; 4-Adequate 3-Maintenance or minor repair needed  
2-Serious repair needed; 1- Urgent dam safety issue – action now - Contact owner and dam safety directly

General	Rating
Structures below dam <input type="checkbox"/> New <input type="checkbox"/> Existing <input type="checkbox"/> Request Dam Safety review of hazard rating	
Distance to dam Dwelling _____ feet Paved public road _____ feet Other building _____ feet	
Vehicle access <input checked="" type="checkbox"/> All weather road <input type="checkbox"/> Dirt road <input type="checkbox"/> Cross country	4
Detail:	

Reservoir	Pool level: <u>4371.7</u> Point of Reference: <input type="checkbox"/> Crest <input checked="" type="checkbox"/> Gage _____	Rating
Minimum freeboard	Vertical distance from debris line to lowest place on crest _____ ft.	—
Debris	<input type="checkbox"/> Floating Debris/Trash <input type="checkbox"/> Log Boom <input type="checkbox"/> Unusual Conditions	—
Detail:		

Spillway	<input type="checkbox"/> Earth <input type="checkbox"/> Rock <input checked="" type="checkbox"/> Concrete <input type="checkbox"/> Other	Rating
Modifications	<input checked="" type="checkbox"/> None <input type="checkbox"/> Reduction in capacity <input type="checkbox"/> Feature not on design	—
Approach Channel	<input checked="" type="checkbox"/> Clear <input type="checkbox"/> Trees/brush <input type="checkbox"/> Debris <input type="checkbox"/> Erosion	4
Control Section	<input type="checkbox"/> Concrete <input type="checkbox"/> Rock <input type="checkbox"/> Soil <input type="checkbox"/> Culvert <input type="checkbox"/> Unstable Width _____ Depth _____	—
Flashboards/Gate	<input type="checkbox"/> None <input type="checkbox"/> In place <input type="checkbox"/> Operational <input type="checkbox"/> Deteriorated	—
Discharge Channel	<input checked="" type="checkbox"/> Clear <input type="checkbox"/> Trees/brush <input type="checkbox"/> Leakage <input type="checkbox"/> Headcutting ( _____ feet from spillway control section, depth _____ feet.)	4
Stilling basin	<input type="checkbox"/> N/A <input checked="" type="checkbox"/> Functional <input type="checkbox"/> Minor Erosion <input type="checkbox"/> Severe Erosion/Undercutting	4
Aux. Spillway	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (use comments below)	—
Detail:		

Seepage/Leakage	Rating
Serious conditions <input type="checkbox"/> Leakage <input type="checkbox"/> Piping <input type="checkbox"/> Discolored water <input type="checkbox"/> Boils	—
Locations* <input type="checkbox"/> No evidence <input type="checkbox"/> Center <input type="checkbox"/> Left <input type="checkbox"/> Right <input type="checkbox"/> Around pipe <input type="checkbox"/> On dam _____	—
Flow <input type="checkbox"/> Wet vegetation <input type="checkbox"/> Spongy <input type="checkbox"/> Standing water <input type="checkbox"/> Flow _____ gpm	—
Toe drains <input type="checkbox"/> None <input type="checkbox"/> Working <input type="checkbox"/> Damaged <input type="checkbox"/> Buried	—
Detail:	

Conduit	Control: <input checked="" type="checkbox"/> Manual <input type="checkbox"/> Power <input type="checkbox"/> Other <input type="checkbox"/> Conduit Control missing	Rating
Inlet	<input checked="" type="checkbox"/> Submerged <input type="checkbox"/> Debris on Trash Rack <input type="checkbox"/> Deterioration	—
Trickle tube	<input checked="" type="checkbox"/> None <input type="checkbox"/> Screened <input type="checkbox"/> Blockage <input type="checkbox"/> Deterioration	—
Control/Stem	<input checked="" type="checkbox"/> Operable <input type="checkbox"/> Damaged <input type="checkbox"/> Missing <i>CONTROL STEMS ARE BENT</i>	3+
Valve(s) cycling	<input type="checkbox"/> Frozen <input type="checkbox"/> Unknown <input type="checkbox"/> Past year <input checked="" type="checkbox"/> Frequent <i>DON'T CLOSE</i>	3
Pipe	Diameter/Size: _____ Material: _____ Condition: _____	—
Primary outlet	<input type="checkbox"/> Overgrown <input type="checkbox"/> Clean <input type="checkbox"/> Pressurized <input type="checkbox"/> Leaking _____ gpm	—
Other outlet(s)	<input type="checkbox"/> Yes <input type="checkbox"/> No Type(s): _____ Diameter(s): _____ in.	—
Detail:		

Structure of dam	<input type="checkbox"/> Earth <input type="checkbox"/> Rock <input checked="" type="checkbox"/> Concrete <input type="checkbox"/> Other	Rating
Distress	<input checked="" type="checkbox"/> Cracks - offset _____ in <input type="checkbox"/> Landslide(s) <input type="checkbox"/> Sinkhole(s) <input type="checkbox"/> Crest Settlement <input type="checkbox"/> Narrow crest <input type="checkbox"/> Wave erosion <input type="checkbox"/> Trampling <input type="checkbox"/> Surface erosion	2
Locations*	<i>SPALLS, CRACKS, VEG GROWING IN CRACKS - ON ALL AREAS OF DAM</i>	2
Other	Describe: _____	—
Aux. dike (s)	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> over 5	—
Animals	<input type="checkbox"/> Nutria <input type="checkbox"/> Badger Other: _____ <input type="checkbox"/> Unknown	Rating
Burrows	<input type="checkbox"/> Observed max diameter _____ in max depth _____ ft <input type="checkbox"/> Trails	—
Locations*		—
Vegetation		Rating
Cover	<input type="checkbox"/> Low grass <input type="checkbox"/> high grass <input type="checkbox"/> brush <input type="checkbox"/> blackberries <input type="checkbox"/> small trees <input type="checkbox"/> large trees	—
Locations*		—
Impairs inspection	<input type="checkbox"/> toe seepage <input type="checkbox"/> conduit outlet <input type="checkbox"/> spillway <input type="checkbox"/> upstream face <input type="checkbox"/> downstream face	—
Detail:		

\*Locations – Upstream face, Crest, Downstream face, Left and Right abutments, Toe

Expedited Re-inspection Needed: ☐ Next Inspection Date: \_\_\_\_\_

Other Issues or Additional Detail Needed:

---



---



---